

[Home](#)

[Back to westernhat2 page](#)

Seam allowance 1/2in.

Grain Line

Westernhat 2
brm
four sheets

Bonding line Aa

DRCOS
SITE: <http://www.drcos.intl/>
MAIL: info@drcos.com
Twitter: <https://twitter.com/drcos>
facebook: <https://www.facebook.com/drcos.com>

Westernhat
top
interfacing(h
on

Bonding line Aa



Bonding line A

DRCOS

SITE <http://www.dr-cos.info/>
MAIL info@dr-cos.com
Twitter https://twitter.com/drcos_com
facebook <https://www.facebook.com/drcoscom>

size
7 1/2
23.5in.


size
7 1/2
23.5in.

DRCOS

SITE <http://www.dr-cos.info/>
MAIL info@dr-cos.com
Twitter https://twitter.com/drcos_com
facebook <https://www.facebook.com/drcoscom>

Seam allowance 1/2in.

Bonding line Ba




Westernhat 2
Top
two sheets

Grain Line



size
7 1/2
23.5in.



interfa

Bonding line AB

bias & wire

size
7 1/2
23.5in.



DRCOS

Website: <http://www.drc-os.info/>
Email: info@drc-os.com
Twitter: https://twitter.com/drcos_com
Facebook: <https://www.facebook.com/drcoscom>

Bonding line Aa

Bonding line Ab

ernhat 2
top
acing (heavy weight)
one sheets

size
7 1/2
23.5in.

Bonding line BA

2
(ht)

Bonding line BA

Westernhat 2
brim
interfacing(heavy weight)
two sheets

Bonding line Ba

DRCOS

SITE <http://www.dr-cos.info/>
MAIL info@dr-cos.com
Twitter https://twitter.com/@drcos_com
facebook <https://www.facebook.com/drcoscom>

Bonding line Bb



Westernhat 2
side
interfacing(heavy weight)
one sheets

Bonding line

COS
www.dr-cos.com
info@dr-cos.com
https://twitter.com/@drcos_com
<https://www.facebook.com/drcoscom>

