


[Home](#)
[Back to UVhat page](#)

DRCOS
SITE <http://dr-cos.com>
MAIL info@dr-cos.com
Twitter [@drcos_com](https://twitter.com/@drcos_com)
facebook <https://www.facebook.com/drcoscom>



UV Hat
Side
one sheets

Seam allowance 1/2in.




Bonding line AA

Bonding line Aa



DRCOS
SITE <http://dr-cos.com>
MAIL info@dr-cos.com
Twitter [@drcos_com](https://twitter.com/@drcos_com)
facebook <https://www.facebook.com/drcoscom>

Crystal Ball

Bonding line AA



Bonding line Ba



- 1. Iron side is
- 2. "side" is
- 3. "top" and "brim" are sewn together
- 4. The surface and the
- 5. two "brims" are sewn
- 6. "side" "brim" is sewn up

Bonding line AA

Seam allowance 1/2in.

How to make
Sorry if I haven't made myself understood (well)
in English. You know I'm poor at English.
Iron on the interfacing(heavy weight) to "Brim"
2: "side" is sew up and loop
3: "top" and "side" sew up and loop
4: "brim" is sew up and the back are same.
5: "top" and "side" are sewn up.
6: "brim" is sewn up.




UV Hat
Brim
two sheets

Bonding line Ca

Bonding line AC





Bonding line Aa

Bonding line Ab

Bonding line BA



Bonding line BA


Bonding line Ba

Bonding line Bb

6 3/4
21.2in.
size

Grain Line

one



Bonding line BB

DRCO
SITE <http://drc.com>
MAIL info@drc.com
TEL: 800-833-3333

Bonding line BB

DRCOS

SITE <http://dr-cos.com>
MAIL info@dr-cos.com
Twitter <https://twitter.com/drcos.com>
facebook <https://www.facebook.com/drcoscom>

UV Hat
Top
one sheets

Seam allowance 1/2in.

Size
6 3/4
21in.

Bonding line Ca

Bonding line Cb

Bonding line BC

DRCOS

SITE <http://dr-cos.com>
MAIL info@dr-cos.com
Twitter <https://twitter.com/drcos.com>
facebook <https://www.facebook.com/drcoscom>


Size
6 3/4
21.2in.

Bonding line Ab



Bonding line Ac

Bonding line CA
t (height)
S



Bonding line Bb

Bonding line CA

Bonding line Bc

Bonding line CB

**UV Hat
Brim
interfacing (heavy weight)
one sheets**