



Seam allowance 5mm



Chinahat 2
brim
two sheets
interfacing (heavy weight)
one sheets



Please c
required
cutting re
and the s
<https://dr>


Bonding line Aa

Seam allowance 5mm



DRCOS
SITE <https://dr-cos.info/en> <https://dr-cos.com/tp>
MAIL info@dr-cos.com
Twitter <https://twitter.com/dr-cos>
Pinterest <https://www.pinterest.jp/dr-cosinfo>

Chinahat 2
Hat Parts
six sheets



Brim position

Bonding line AA

nce 5mm

Please check here for the
required fabric length images,
cutting reference images,
and the step-by-step sewing instructions.
<https://dr-cos.info/fp-cloche4.html>



DRCOS
SITE [https://dr-cos.info\(en\)](https://dr-cos.info(en)) <https://dr-cos.com/jp>
MAIL info@dr-cos.com
Twitter [@drcos_com](https://twitter.com/@drcos_com)
Pinterest <https://www.pinterest.jp/drcosinfo>

Seam allowance 1cm

Bonding line Aa

Bonding line Ab

Bonding line BA