




Lapel

Collar attachment position

MEN'S size **S**

Jacket
Front body
cut two

Button & buttonhole position

Bonding line AA

Bonding line Aa

Seam allowance 2cm



Center line



Button & buttonhole position

Bonding line AB



How to make buttonholes.
Please refer to this page
<https://www.dr-cos.info/kt-buttonhole.html>



How to sew on buttons.
Please refer to this page
<https://www.dr-cos.info/kt-button.html>



How to Serge/overlock (sewing machine & overlock sewing machine).
Please refer to this page
<https://www.dr-cos.info/kt-serge.html>

Pocket position



Bonding line AB

Cutting line at the lining edge (seam allowance: 1 cm)

Seam allowance 5cm

Bonding line Ca

DRCOS

SITE: <https://drcosinfo.eu>
MAIL: info@drcos.com
TWITTER: https://twitter.com/drcos_com
PHONE: <https://www.phonetel.jp/drcosinfo>

Jacket
Front body side interfacing
cut two

MEN'S  size

Bonding line AC

DRCOS

SITE <https://dr-cos.info/en> <https://dr-cos.com/jp>
MAIL info@dr-cos.com
Twitter [@drcos_com](https://twitter.com/@drcos_com)
pinterest <https://www.pinterest.jp/drcosinfo>

MEN'S



Jacket
Collar interfacing
cut one


Seam allowance 1cm

Bonding line BA



Bonding line Aa

Bonding line Ab



Grain Line

Bonding line BA

Bonding line Bb

Bonding line BB

Jacket
Back body side into
cut two

DRCOS

SITE <https://dr-cos.info/en/>
MAIL info@dr-cos.com
Twitter <https://twitter.com/dr-cos>
Pinterest <https://www.pinterest.jp/dr-cos/info>

Please refer to this page
<https://www.dr-cos.info/kt-serge.html>



cket
de interfacing
two

Bonding line BB

Bonding line Cb

Grain Line

DRCOS
SITE <https://dr-cos.info/en>) <https://dr-cos.com/jp>
MAIL info@dr-cos.com
Twitter https://twitter.com/drcos_com
Pinterest <https://www.pinterest.jp/drcosinfo>

Cutting line at the lining edge (seam allowance: 1 cm)

Seam allowance 5cm

Bonding line Ca

Bonding line BC



DRCOS

SITE <https://dr-cos.info/en> <https://dr-cos.com/jp>

MAIL info@dr-cos.com

Twitter [@drcos_com](https://twitter.com/@drcos_com)

pinterest <https://www.pinterest.jp/drcosinfo>


Bonding line Ab

Bonding line Ac

MEN'S

Jacket
Back body
cut two
Lining
cut two

Bonding line CA



Bonding line CA

Grain Line
Bonding line Bc

Seam allowance 2cm

Bonding line Bb

Bonding line CB

DRCOS

SITE <https://dr-cos.info/en> <https://dr-cos.com/lp>
MAIL info@dr-cos.com dr-cos.com
Twitter <https://twitter.com/dr-cosinfo>
Pinterest <https://www.pinterest.jp/dr-cosinfo>

MEN'S



Bonding line CB

Cutting line at the lining edge

Seam allowance

Bonding line Cb


Seam allowance 2cm

Bonding line Cc

Jacket
Back body side
cut two
Lining
cut two



Bonding line CC



Bonding line Ac

Bonding line Ad

Bonding line DA

S

ME

Front b

et
body
wo
ng
wo



Bonding line DA

Bonding line Bc


Grain Line

Bonding line Bd

Please check the required fabric cutting reference and the step-by-step instructions at <https://dr-cos.it>



Bonding line DB



Bonding line DB

Bonding edge (seam allowance: 1 cm)

Seam allowance 5cm

Bonding line Cc

Seam allowance 5cm

Cutting line at the lining edge (seam allowance: 1 cm)

Bonding line Cd

Bonding line DC

Bonding line Ad

Bonding line Ae

DRCOS

SITE <https://dr-cos.info/en> <https://dr-cos.com/jp>
MAIL info@dr-cos.com
Twitter [@drcos_com](https://twitter.com/@drcos_com)
pinterest <https://www.pinterest.jp/drcosinfo>

EN'S  **S**

Jacket
nt body interfacing
cut two

Bonding line EA

Bonding line EA

Bonding line Bd

Bonding line Be

check here for the
d fabric length images,
reference images,
e step-by-step sewing instructions.
dr-cos.info/fp-jacket.html



Bonding line EB

quiescipdf/1se9uirt...
u00'sc

Jacket

Front body side cut two

Lining cut two

Bonding line Ce

Seam allowance 2cm

Bonding line EB


Pocket position

Baste

Bonding line Cd

Bonding line EC


Grain Line



Bonding line Ae



Bonding line FA



Seam allowance 1cm



Bonding line Af

Bonding line FA

Jacket
Lining
cut two

MEN'S



Bonding line Be


Jacket
Facing
cut two

Bonding line Bf



Bonding line FB

DRCOS
SITE <https://dr-cos.info/en/>
MAIL info@dr-cos.com
TWITTER <https://twitter.com/dr-cos>
PINTEREST <https://www.pinterest.jp/dr-cos/info>



Bonding line FB

Bonding line Cf

Bonding line FC

DRCOS


SITE <https://dr-cos.info/en> <https://dr-cos.com/jp>
MAIL info@dr-cos.com
Twitter https://twitter.com/dr-cos_com
Pinterest <https://www.pinterest.jp/dr-cosinfo>

MEN'S
size
S

Jacket

Bonding line Ce

DR COS
@dr-cos_com (jp)
@dr-cos_com (en)
https://dr-cos.info/en
https://dr-cos.com/jp



S

Bonding line Af

Bonding line GA

Scale: 1 cm

Bonding line Ag

ME

Bonding line Bf

Bonding line GA

Bonding line GB

OW

Bonding line Bg



SC

Bonding line GB


Bonding line Cf

Bonding line Cg

DRCOS

SITE <https://dr-cos.info/en> <https://dr-cos.com/jp>
MAIL info@dr-cos.com
Twitter https://twitter.com/dr-cos_com
Pinterest <https://www.pinterest.jp/dr-cosinfo>

Bonding line GC



DRCOS
SITE <https://dr-cos.info/en> <https://dr-cos.com/jp/>
MAIL info@dr-cos.com
Twitter <https://twitter.com/dr-cos>
Pinterest <https://www.pinterest.jp/dr-cos/info>

MEN'S
size
Jacket
Outer sleeve cut two
Lining cut two

Line Bg


Bonding line HA

Seam allowance 2cm

Bonding line Bh

Bonding line HB

Bonding line HB



Bonding line Cg

MEN'S
size

Jacket
Inner sleeve cut two
Lining cut two

Grain Line

Seam allowance 2cm

Bonding line HC

Bonding line Ch

Bonding line IA


DRCOS
SITE <https://dr-cos.info/en> <https://dr-cos.com/jp>
MAIL info@dr-cos.com
Twitter <https://twitter.com/dr-cosinfo>
Pinterest <https://www.pinterest.jp/dr-cosinfo>

Grain Line

Jacket
Collar
cut two

size

Bonding line



Bonding line

MEN'S

size

Jacket
Flap cut two

DRCOS

SITE <https://dr-cos.info/en> <https://dr-cos.com/jp>
MAIL info@dr-cos.com
Twitter [@drcos_com](https://twitter.com/@drcos_com)
pinterest <https://www.pinterest.jp/drcosinfo>

Seam allowance 1cm

Bonding line Ch

Cutting line at the lining edge (seam allowance: 1 cm)

Seam allowance 4cm

Bonding line IC