




Grain Line

Bonding line AA

Seam allowance 1/2in

Seam allowance 2in


Cutting line at the lining edge (seam allowance: 1/2in)

Bonding line AA

Seam a

Jacket
Back body
cut two
Lining
cut two

Bonding line Ba



Bonding line AB


Bonding line AB

DRCOS
SITE <https://dr-cos.info/en> <https://dr-cos.com/jp>
MAIL info@dr-cos.com
Twitter https://twitter.com/dr-cos_com
Pinterest <https://www.pinterest.jp/dr-cosinfo>

Bonding line Ca

Bonding line AC

Bonding line AC



Jacket
Facing
cut two



Bonding line Da

Jacket
Lining
cut two

Bonding line AD

Bonding line AD



DRCOS

SITE [https://dr-cos.info\(en\)](https://dr-cos.info(en)) [https://dr-cos.com\(jp\)](https://dr-cos.com(jp))

MAIL info@dr-cos.com

Twitter [@drcos_com](https://twitter.com/@drcos_com)


pinterest <https://www.pinterest.jp/drcosinfo>

Seam allowance 1/2in



Bonding line Ea

Bonding line AE



Seam allowance 2in

Cutting line at the lining edge (seam allowance: 1/2in)

Grain Line

Seam allowance 1/2in

Bonding line BA

Bonding line Aa

Bonding line Ab

DRCOS
SITE <https://drcos.info/en> <https://drcos.com/jp/>
MAIL info@drcos.com
Twitter https://twitter.com/drcos_com
Pinterest <https://www.pinterest.jp/drcosinfo>

Bonding line Ba

Jacket
Back body side
cut two
Lining
cut two




Bonding line BA


Seal

Bonding line Bb

Bonding line BB

Front





size

Jacket interfacing
cut two


DRCOS
SITE: <https://drcos.info/en> <https://drcos.com>
MAIL: info@drcos.com
Twitter: https://twitter.com/drcos_com
Pinterest: <https://www.pinterest.jp/drcosinfo>

Bonding line Ca

Bonding line Cb

DRCOS
SITE: <https://drcos.info/en> <https://drcos.com>
MAIL: info@drcos.com
Twitter: https://twitter.com/drcos_com
Pinterest: <https://www.pinterest.jp/drcosinfo>

Bonding line BC



Bonding line BC

Bonding line BD


Bonding line Da


Bonding line Db

jacket
by interfacing
out two

ket
ng
wo

for the
with images,
pp sewing instructions.
o-jacket.html





Jacket

by interfacing

Bonding line BD

Bonding line Eb

Bonding line Ea

DRCOS
SITE <https://dr-cos.info/en> <https://dr-cos.com/jp>
MAIL info@dr-cos.com
Twitter https://twitter.com/dr-cos_com
Pinterest <https://www.pinterest.jp/drcosinfo>

Bonding line BE

Line 




How to sew darts.
Please refer to this page
<https://www.dr-cos.info/kt-darts.html>

CA

Seam allowance 1/2in

Pocket position

Baste 

Jacket
Front body side cut two
Lining cut two

Cutting line at the lining edge (seam allowance: 1/2in)

Seam allowance 2in

Bonding line Ab

Bonding line Ac

Grain Line

darts

ts.html



CA

Bonding line Bb


Bonding line Bc

Bonding line CB

DRCOS
SITE <https://dr-cos.info/en> <https://dr-cos.com/jp>
MAIL info@dr-cos.com
Twitter https://twitter.com/dr-cos_com
Pinterest <https://www.pinterest.jp/dr-cos/info>



Bonding line CB



Bonding line Cb

Bonding line CC

DRCOS
SITE: <https://dr-cos.info/en> | <https://dr-cos.com/jp>
MAIL: info@dr-cos.com
Twitter: <https://twitter.com/dr-cos.com>
Pinterest: <https://www.pinterest.jp/drcosinfo>

Bonding line Cc

S
M
T
p

Jack
Front body in
cut to

Out
1

Please check here for the
required fabric length image,
cutting reference images,
and the step-by-step sewing
<https://dr-cos.info/tp-jacket>




Bonding line Db

Bonding line CD

Seam allowance 1/2in

Bonding line CC

Bonding line Dc



How to Serge/overlock (sewing machine & Please refer to this page
<https://www.dr-cos.info/kt-serge.html>



Pocket position

How to make buttonholes.
Please refer to this page
<https://www.dr-cos.info/kt-buttonhole.html>



Center line



Grain Line

Cutting line at the lining edge (seam allowance: 1/2in)

Seam allowance 2in

Seam allowance 1/2in



size

Bonding line Bc

chine & overlock sewing machine).

nl

Jacket
Front body
cut two

Bonding line DB

How to sew on buttons.
Please refer to this page
<https://www.dr-cos.info/kt-button.html>



Button & buttonhole position



Bonding line DA

Sea

Bonding line Bd

Label

Bonding line DB

Label

Collar attachment position



Bonding line Cc

Bonding line Cd




DRCOS

SITE <https://dr-cos.info/en>) <https://dr-cos.com/jp>)
MAIL info@dr-cos.com
Twitter https://twitter.com/@drcos_com
pinterest <https://www.pinterest.jp/drcosinfo>

Bonding line DC

Bonding line DC


Bonding line Dc



Bonding line Dd


Jacket
Outer sleeve cut two
Lining cut two

Bonding line DD



Bonding line Ad

Bonding line Ae



Bonding line


DRCOS

SITE <https://dr-cos.info/en> <https://dr-cos.com/jp>
MAIL info@dr-cos.com
Twitter [@drcos_com](https://twitter.com/@drcos_com)

Bonding line

DRCOS

SITE [https://dr-cos.info\(en\)](https://dr-cos.info(en)) [https://dr-cos.com\(jp\)](https://dr-cos.com(jp))
MAIL info@dr-cos.com
Twitter [@drcos_com](https://twitter.com/@drcos_com)
pinterest <https://www.pinterest.jp/drcosinfo>



Seam allowance 1/2in


Jacket
Inner sleeve cut two
Lining cut two

Bonding line EB

Grain

Bonding line Bd

Bonding line Be



Bonding line EC



Jacket
body side interfacing
cut two

Bonding line Dd



Bonding line ED

Bonding line De

Bonding line ED

Jacket
Collar
cut two
Collar interfacing
cut one

Seam allowance 1 1/2 in

Grain Line

DRCOS
SITE <https://drcos.info/en> <https://drcos.com>
MAIL info@drcos.com info@drcos.com
Twitter https://twitter.com/info_drcos
Pinterest <https://www.pinterest.jp/drcosinfo>

Bonding line EE

Bonding line Ed

Bonding line Ee