

(n)

(d)uoc

Bending line Aa

allowance 1/2in

Bending line AA

in Line

Cutting line at the lining edge (seam allowance: 1/2in)

Seam allowance 2in



Jacket
Back body
cut two
Lining
cut two

Bonding line AB

Bonding line AA

Grain Line



Seam allowance

Bonding line Ba

Bonding line AB

DRCOS
SITE <https://dr-cos.info/en> <https://dr-cos.com/jp>
MAIL info@dr-cos.com
Twitter https://twitter.com/dr-cos_com
Pinterest <https://www.pinterest.jp/dr-cosinfo>

Bonding line Ca

Bonding line AC

Bonding line AC

MEN'S 

Jacket
Facing
cut two

Bonding line AD



MEN

Jacket
Lining
cut two

Bonding line AD



Seam allowance 1/2in

Bonding line AE

Bonding line Aa



Seam allowance 1/2in

Bonding line BA

cut two

DRCOS

SITE <https://drcos.info/en> [https://drcos.com\(jp\)](https://drcos.com/jp)
MAIL info@drcos.com
Twitter https://twitter.com/drcos_com
Pinterest <https://www.pinterest.jp/drcosinfo>

Cutting line at the lining edge (seam allowance: 1/2in)

Seam allowance 2in

Grain Line
Bonding line Ab

allowance: 1/2in)

Bonding line Ba

Jacket
Back body side
cut two
Lining
cut two

MEN'S



Bonding line Ba

Bonding

COS

on
(en) <https://dr-cos.com/ip>
om/@dr-cos
interest, info

Jacket
Back body side interfacing
cut two



MEN'S

two

Bonding line Bb


Bonding line Ca

Bonding line Bb

Front body

W


DRCOS
SITE <https://dr-cos.info/en> <https://dr-cos.com>
MAIL info@dr-cos.com
Twitter https://twitter.com/dr-cos_jp
Pinterest <https://www.pinterest.jp/dr-cosinfo>



Bonding line Cb

Bonding line BC

DRCOS
SITE <https://dr-cos.info/en> <https://dr-cos.com/jp>
MAIL info@dr-cos.com
Twitter https://twitter.com/dr-cos_jp
Pinterest <https://www.pinterest.jp/dr-cosinfo>



Bonding line BC

Bonding line BD

Bonding line Db

S
size
Bonding
EN'S

acket
ning
t two

for the
th images,
p sewing instructions.
o-jacket.html

t two
y interacting

ack
y interfacing
two




Bonding line Eb

DRCOS
SITE <https://dr-cos.info/en> <https://dr-cos.com/jp>
MAIL info@dr-cos.com
Twitter https://twitter.com/dr-cos_com
Pinterest <https://www.pinterest.jp/dr-cosinfo>

Bonding line BD

Bonding line BE

Bonding line Ea



How to Serge/overlock (sewing machine & overlock)
Please refer to this page
<https://www.dr-cos.info/kt-serge.html>

Pocket position



Seam allowance 1/2in

Bonding line CA

Baste

Pocket position



Bonding line Ac

Seam allowance 1/2in

Seam allowance 2in

Bonding line Ab


Grain Line

line & overlock sewing machine).

Sea


Bonding line CA

Jacket
Front body side cut two
Lining cut two



Bonding line Bb

Bonding line Bc



Bonding line CB

Bonding line CB

DRCOS
SITE <https://dr-cos.info/en> <https://dr-cos.com/jp>
MAIL info@dr-cos.com
Twitter https://twitter.com/dr-cos_com
Pinterest <https://www.pinterest.jp/drcosinfo>

Bonding line Cb

Bonding line Cc

Bonding line CC

allowance 1.5in
edge (seam allowance: 1/2in)

From body in
cut two

Bonding line CD


Bonding line CC

Bonding line Dc

Bonding line Db



Please check here for the
required fabric length image,
cutting reference images,
and the step-by-step sewing
<https://dr-cos.info/tp-jacket>.



Bonding line Ac

Bonding line Ad

Seam allowance 2in

Cutting line at the lining edge (seam allowance: 1/2in)

How to make buttonholes.
Please refer to this page
<https://www.dr-cos.info/kt-buttonh>



Center line



Grain Line



Bonding line DA

Seam allowance 1/2in

MENS

Jacket
Front body
cut two

Label

Bonding line DB

Button & buttonhole position

How to sew on buttons.
Please refer to this page
<https://www.dr-cos.info/kt-button.html>



buttonhole.html



Bonding line DA



Bonding line Bc

Bonding line Bd

S

Bonding line DB

Collar attachment position

Bonding line Cc

Bonding line Cd


DRCOS

SITE [https://dr-cos.info\(en\)](https://dr-cos.info(en)) [https://dr-cos.com\(jp\)](https://dr-cos.com(jp))
MAIL info@dr-cos.com
Twitter [@drcos_com](https://twitter.com/@drcos_com)
pinterest <https://www.pinterest.jp/drcosinfo>

Seam allowance

Cutting line at the lining edge (s

Bonding line DC



Bonding line Dc

Grain Line

Bonding line DC

Bonding line Dd

Bonding line DD

Seam allowance 1/2in

Bonding line DD

Jacket
Outer sleeve cut two
Lining cut two




DRCOS
SITE <https://dr-cos.info/en> <https://dr-cos.com/jp>
MAIL info@dr-cos.com
Twitter https://twitter.com/dr-cos_com
Pinterest <https://www.pinterest.jp/dr-cosinfo>

Bonding line DE

Bonding line Ec

Bonding line Ed



DRCOS

SITE <https://dr-cos.info/en> <https://dr-cos.com/jp>
MAIL info@dr-cos.com
Twitter https://twitter.com/dr-cos_com
pinterest <https://www.pinterest.jp/drcosinfo>

Grain Line

Jacket
Collar
cut two
Collar interfacing
cut one

Seam allowance 1/2in

Bonding line Bd

Bonding line EA



MEN'S

Bonding line Be

Bonding line EB

Bonding line EB



Jacket
Back body side interfacing
cut two

Bonding line Cd

Bonding line Ce

Bonding line EC

Bonding line EC

Bonding line Dd

Bonding line De

DRCOS

SITE <https://dr-cos.info/en> <https://dr-cos.com/jp>
MAIL info@dr-cos.com
Twitter [@drcos_com](https://twitter.com/@drcos_com)
pinterest <https://www.pinterest.jp/drcosinfo>

MEN'S  **S**

Jacket
Inner sleeve cut two
Lining cut two

Seam allowance 1/2in

Bonding line ED

Bonding line Ed

Bonding line Ee

1/2in

Bonding line ED

Bonding line EE



Cutting line at the lining edge (seam allowance: 1/2in)

Seam allowance 1.5in