

Seam allowance 1cm

Grain Line

64

size

DRCOS
SITE <https://dr-cos.info/en> <https://dr-cos.com/jp>
MAIL info@dr-cos.com
Twitter <https://twitter.com/dr-cos.com>
Pinterest <https://www.pinterest.jp/drcosinfo>

grommet

DRCOS

SITE <https://dr-cos.info/en> <https://dr-cos.com/jp>
MAIL info@dr-cos.com
Twitter <https://twitter.com/dr-cos.com>
Pinterest <https://www.pinterest.jp/drcosinfo>

Bonding line Aa

6

size

Bonding line AA

Bonding line AA



Bonding line Ba

two sheets

Grain Line



Seam allowance




Bonding line AB



Westernhat
side
interfacing(heavy weight)
one sheets





Westernhat
brim
four sheets

bias & wire

Bonding line Aa

Bonding line Ab

Bonding line BA

size
64

Westernhat
top
interfacing
(heavy weight)
sheets

DRCOS
SITE [https://dr-cos.info\(en\)](https://dr-cos.info(en)) [https://dr-cos.com\(jp\)](https://dr-cos.com(jp))
MAIL info@dr-cos.com
Twitter https://twitter.com/dr-cos_com
Pinterest <https://www.pinterest.jp/drcosinfo>

interfacing
(heavy weight)
one sheets

Bonding line BA

Westernhat
brim
interfacing (heavy weight)
two sheets

Bonding line Ba

Bonding line Bb

Westernhat
Top
two sheets



allowance 1cm

Bonding line BB


RCOS
info(en) <https://dr-cos.com/jp>
info@dr-cos.com
/twitter.com/@dracos
/www.pinterest.jp/dracosinfo

Bonding line Ca

Bonding line BB



*Westernhat
side
two sheets*



Seam allowance 1cm

Bonding line Cb