

Westernhat 2
brim
two sheets
enfacing(heavy weight)

Please check here for the
required fabric length images,
cutting reference images,
and the step-by-step sewing instructions.
<https://dr-cos.info/tp-westernhat2.html>



DRCOS
SITE <https://dr-cos.info/en/> <https://dr-cos.com/jp/>
MAIL info@dr-cos.com info@dr-cos.jp
Twitter <https://twitter.com/dr-cos.com>
Pinterest <https://www.pinterest.jp/drcosinfo>

Seam allowance 1/2in.

Westernhat 2
Top
two sheets

Bonding line Aa

Bonding line AA

interfaci
West

DRCOS
SITE <https://dr-cos.info/en/> <https://dr-cos.com/pt/>
MAIL info@dr-cos.com
Twitter https://twitter.com/dr-cos_com
Pinterest <https://www.pinterest.jp/drcosinfo>

Bonding line Aa

Grain Line

West




inter

Bonding line Ab

DRCOS
SITE <https://dr-cos.info/en/> <https://dr-cos.com/pt/>
MAIL info@dr-cos.com
Twitter https://twitter.com/dr-cos_com
Pinterest <https://www.pinterest.jp/drcosinfo>

bias & wire

Bonding line BA



size

56

Westernhat 2
top
interfacing (heavy weight)
one sheets

DRCOS

SITE <https://drc-cos.info/en> <https://drc-cos.com/jp>
MAIL info@drc-cos.com
Twitter https://twitter.com/drcos_com
Pinterest <https://www.pinterest.jp/drcosinfo>

Seam allowance 1/2in.

Westernhat 2
brim
four sheets

size

56





grommet

Bonding line Ac

Bonding line CA

Bonding line Ac



eight)



DRCOS
SITE [https://dr-cos.info\(en\)](https://dr-cos.info(en)) [https://dr-cos.com\(jp\)](https://dr-cos.com(jp))
MAIL info@dr-cos.com
Twitter https://twitter.com/@drcos_com
Pinterest <https://www.pinterest.jp/drcosinfo>

Bonding line Ad



DRCOS
SITE [https://dr-cos.info\(en\)](https://dr-cos.info(en)) [https://dr-cos.com\(jp\)](https://dr-cos.com(jp))
MAIL info@dr-cos.com
Twitter https://twitter.com/@drcos_com
Pinterest <https://www.pinterest.jp/drcosinfo>

hat 2
ets

m allowance 1/2in.

Bonding line EA